Honeywell

HH400_USB COM Port support!

Scan the following configuration bar code in order to enable the USB COM Port.

(3)   **USB Serial**

USB Serial Interface

The Windows os is detecting a new hardware and tries to install a driver but fails.

Go to the Device Manager and search for the HH400.

Right Mouse click on the HH400 > Update Driver Software……..

Search for the driver where it is saved locally > HH400Vcom_Driver_170113 > click on install.

There is a Windows Security Warning > click on 'Install this driver software anyway'.

The System is updating the driver, which will take a few seconds!

After the successful installation of the USB COM Port driver following information is seen:

Check the Device Manager for the assigned COM Port!